













3020019






A x 8




Ø8x35 mm

B x 2




Ø6x30 mm

C x 2




Ø7x50 mm

D x 4



Ø7x60 mm

E x 1



4 mm

F x 4




20 mm

G x 4




Ø15x12 mm

H x 6



Ø5x44 mm

I x 3



3,5x16 mm

J x 4



Ø6,3x13 mm

K x 2



4x9 mm

L x 3




Ø3x20 mm

M x 4



10x10 mm

N x 1




O x 2



Ø 12x10 mm

P x 2




310 mm

Q x 2



20 mm

R x 1




S x 4




14 mm



T x 1




5 mm

U x 1







BOX 1/1:




363x135x16 mm



363x135x16 mm




400x385x16 mm




400x385x16 mm




376x145x3 mm



396x129x18 mm




343x307x3 mm




300x100x12 mm













333x85x12 mm






300x100x12 mm



1










2






3

G x 4  Ø15x12 mm	F x 4  20 mm	
---	---	--






4







R x 1 	I x 2  3,5x16 mm	
--	---	--



5




6








7

M x 4
10x10 mm












$XX = YY \equiv 90^\circ$





8




N x 1

J x 1
3,5x16 mm








9

H x 2  Ø5x44 mm	B x 2  Ø6x30 mm	
--	--	---



10

C x 2  Ø7x50 mm	E x 1  4 mm	
--	--	--






11

O x 2

 Ø12x10 mm

Q x 2







 20 mm



12

L x 3

 Ø3x20 mm



13

K x 2



4x9 mm

