












Basic Plus

Szafa 3D






A x 20




Ø8x35 mm

B x 16



Ø7x50 mm

E x 1




4 mm

F x 10




20 mm

G x 60




1,2x25 mm

G4 x 5




H x 10




22x9x2 mm

I x 2




J x 22



3,5x16 mm

J6 x 11




4x30 mm

M x 12




Ø6,3x13 mm

M4 x 6




O x 12




Ø5mm


R1 x 6




R2 x 3




S x 9




AD1 x 2




AE x 1



707 mm




BOX 1/1:




48

1738x499x16 mm




56

1738x499x16 mm



57

1738x483x16 mm




58

1107x500x16 mm




59

1107x500x16 mm




60

713x400x16 mm



61 **x3**

344x400x16 mm




52

1764x366x16 mm




53

1732x70x16 mm




63 **x2**

1764x336x16 mm



62

1738x50x16 mm




55

1766x732x3 mm














65

1766x366x3 mm









1

A x 16  Ø8x35 mm	S x 6 	J x 1  3,5x16 mm	AD1 x 1 	O x 6  Ø5 mm	
---	--	---	--	---	---







2

A x 4  Ø8x35 mm	O x 6  Ø5 mm	M. x 6  Ø6,3x13 mm	M4 x 6 	
--	---	---	---	---









3

M. x 6  Ø6,3x13 mm	
---	---





4

B x 4  Ø7x50 mm	E x 1  4 mm	F x 4  20 mm	
--	--	---	--






5



B x 12  Ø7x50 mm	E x 1  4 mm	
---	--	--



6



7



$XX = YY \equiv 90^\circ$


8

G x 60








1.2x25 mm

H x 10




22x9x2 mm



9

I x 2















J x 2







3,5x16 mm

S x 3









10

J6 x 6  4x30 mm	F x 6  20 mm		
--	---	--	---














11

R1 x 6 	J x 18  3,5x16 mm	R2 x 3 	
---	--	---	---






12

AE x 1  707 mm	J x 1  3,5x16 mm	AD1 x 1 	
---	---	--	---



13



14

J6 x 4



4x30 mm

