













MANUAL INSTRUCTION





1		ST4X30	X8
2		Φ6x30	X8
3		ST4X25	X8
4		ST4X10	X4
5		ST4X10	X8
6		ST4X12	X8
7			X4
8			X8
9			X4
10			X2
11			X2
12			X2
13			X8
14			X2



<p>3</p>  <p>X8</p>	<p>4</p>  <p>X4</p>	<p>7</p>  <p>X4</p>	<p>9</p>  <p>X2</p>	<p>10</p>  <p>X2</p>
--	--	--	---	---







13


X4

X4









a




b



c








d



e




















14




X2







12



X2

