














Basic Plus

Podstawa 4S






A x 28




Ø8x35 mm

A2 x 2




Ø8x60 mm

B x 6



Ø7x50 mm

B2 x 16




C x 6




Ø15x12 mm

C1 x 8




Ø15x10 mm

D x 14



Ø5x44 mm

E x 1



4 mm

F x 6




20 mm

F1 x 8



20 mm

G x 40




1,2x25 mm

G4 x 5



J6 x 5




4x30 mm

M x 16



Ø6,3x13 mm

N1 x 8








310 mm


Q x 8




4x9 mm




BOX 1/1:




298x499x16 mm




298x499x16 mm




298x499x16 mm




1107x500x16 mm




548x147x16 mm




548x147x16 mm




548x147x16 mm



548x147x16 mm




1107x500x16 mm



350x100x12 mm

x4



350x100x12 mm


x4




528,5x50x16 mm



496x85x12 mm




1099x326x3 mm











506x357x3 mm

(46) x4







1

A x 16  Ø8x35 mm	M x 8  Ø6,3x13 mm	N1 x 4  310 mm	
---	--	---	---




2




A x 4  Ø8x35 mm	D x 6  Ø5x44 mm	M x 8  Ø6,3x13 mm	N1 x 4  310 mm	
--	--	--	--	---



!!!








!!!



3




A2 x 2
Ø8x60 mm



4

B x 6
Ø7x50 mm

E x 1
4 mm









5

C x 6

 Ø15x12 mm


F x 6





 20 mm





6

G4 x 5




J6 x 5

 4x30 mm



7




$XX = YY \equiv 90^\circ$








8


G x 24



1.2x25 mm



✓




9

A x 8








Ø8x35 mm


D x 8




Ø5x44 mm



x4








x4




10




B2 x 16





x4

11

C1 x 8  Ø15x10 mm	F1 x 8  20 mm	
--	--	---



12





13




G x 16



1.2x25 mm



$XX=YY\equiv 90^\circ$



14

Q x 8



4x9 mm

